

IQ Panel 5/IQ5 HUB/IQ5 NS - 5.0.2 SOFTWARE UPDATE - RELEASE NOTES

TSB #: 260506

DATE: 05/06/26

RE: IQ Panel 5/IQ5 HUB/IQ5 NS - 5.0.2 SOFTWARE UPDATE
RELEASE NOTES & UPDATE INSTRUCTIONS

Release Notes:

Fixes/Improvements:

- Fixed an issue where the siren might keep sounding during a Panel Test
- Improved the connection process performance for IQ Installer with IQ5 family
- Resolved a problem where the panel could reboot while writing to the health memory
- Updated calibration for touchscreen sensitivity
- Modified supervision protocols for the new PGP Heat Detectors (PGP9979, PGP8979)
- Fixed certain rules on PGMs when using W2W (PGxHRDW8, PGxWLSHW8) or IOG (PGP-IOx) that were not working correctly.

Update Instructions:

Compatibility Note: Your IQ Panel must be on software version 5.0.1 or higher and connected to WiFi to install this updated wirelessly.

- 1- Swipe down from the top of the screen and touch "Settings"
- 2- Touch "Advanced Settings"
- 3- Enter a valid installer code (default is 1111)
- 4- Touch "Upgrade Software"
- 5 -Touch "Patch Tag" and enter the patch *iqpanel5.0.2* then touch OK
- 6- Touch "Upgrade Using Network" (Panel must be connected to Wi-Fi). Update will download and install
- 7- Once complete touch "OK" to reboot the Panel. **DO NOT TOUCH THE SCREEN.** The update process will take approximately 5 minutes. After the Panel reboots the home screen will appear and the LED will turn green.