Technical Advisory Bulletin

DSC
From Tyco Security Products

Date: March 19, 2015

To: Global Sales Channel

DLS 5 v1.4 Hotfix - RF5132 Wireless Module Upload

DSC would like to inform you of the release of a DLS 5 v1.40 hotfix that corrects the following issue:

- PowerSeries panel accounts with an RF5132 wireless module could not be uploaded properly.

The update will be displayed as follow on the DLS updater window: