

IQ Panel 5/IQ5 HUB/IQ5 NS - 5.1.0 SOFTWARE UPDATE - RELEASE NOTES

TSB #: 260810

DATE: 08/10/26

RE: IQ Panel 5/IQ5 HUB/IQ5 NS - 5.1.0 SOFTWARE UPDATE
RELEASE NOTES & UPDATE INSTRUCTIONS

Release Notes:

New Features:

- Added Arming Photos feature. IQ Panel 5 can now take a picture on Arming, in addition to Disarming
- WPA3 Wi-Fi security networks are now supported
- Added support for Levven lighting control
- Brilliant NextGen Smart Home integration. Control IQ5 security (arm, disarm, etc) from the Brilliant's in-wall Smart Home Control
- Ability to provision Matter Wi-Fi lights with Alarm.com
- PowerG Automation devices (lights, plugs & locks) are now included in PowerG+ Dealer Lockdown feature
- Added the ability for IQ5 panels to function as Broadband / Wi-Fi only (cell trouble can be disabled)
- Added support on Alarm.com for setting IQ Lock PG relock timer remotely
- Photoframe Screensaver now supports GIF Video
- Added 2 new clocks to Photoframe Screensaver (Digital & Analog)
- Ability to disable the power button (EU Requirement)
- Added the option to have a 90 second siren timeout (Italian requirement)
- Increased maximum allowable "Other Z-Wave Devices" to 40
- Added a setting to allow the panel to send E150 Auxiliary alarm signals to CMS for touchscreen panics
- Added support for double press PowerG panics to send Verified Panic to CMS (EN Grade2)
- Added support for ADC analytic notifications and chime (TTS only, Chime only or Both)
- Added support for redownloading Panel help videos
- Support has been added for adding and deleting PowerG prox tags within the Alarm.com Partner Portal
- Implemented Z-Wave LR as the Default Z-Wave setting on new installs
- Added ability to search by Name or ID when editing or deleting sensors or automation devices
- Adjusted MMH auto install interval from 14 to 2 days (post update after 5.1.0)
- Added support for Czech and Portuguese (Brazil)
- Added support for the following 24 Hour emergency / environmental sensor groups:
 - Group 18 - 24 Hour Bell/Buzzer
 - Group 23 - 24 Hour Supervisory
 - Group 24 - 24 Hour Supervisory Buzzer
 - Group 27 - 24 Hour Fire Supervisory
 - Group 40 - 24 Hour Gas
 - Group 48 - 24 Hour Sprinkler

Fixes/Improvements:

- Improved packet detection for legacy 345MHz & 433MHz SRF devices
- Added support for the new PGP9973 CO (not yet released), including one sound all sound

IQ Panel 5/IQ5 HUB/IQ5 NS - 5.1.0 SOFTWARE UPDATE - RELEASE NOTES

...continued from Page 1

- Added support for ADC sending restorals to CMS on all PG panic buttons (groups 0-7)
- Corrected an issue where sensors programmed as group 25 could annunciate device status randomly
- Corrected an issue where “Other Z-Wave Devices” were being checked by the system health check
- Cellular improvements
- Update to Z-Wave controller firmware & improvements to the SmartStart process
- About screen usability improvements and additional information
- Sensor Test now shows when the sensor was added
- Zigbee device support equivalent to IQ Panel 4 family
- New history log event for when Dealer/Installer enters or exits programming
- New battery graphic displayed if Panel is charging the battery before booting

Update Instructions:

Compatibility Note: Your IQ Panel must be on software version 5.0.1 or higher and connected to WiFi to install this updated wirelessly.

- 1- Swipe down from the top of the screen and touch “Settings”
- 2- Touch “Advanced Settings”
- 3- Enter a valid installer code (default is 1111)
- 4- Touch "Upgrade Software"
- 5 -Touch “Patch Tag” and enter the patch *iqpanel5.1.0* then touch OK
- 6- Touch "Upgrade Using Network" (Panel must be connected to Wi-Fi). Update will download and install
- 7- Once complete touch "OK" to reboot the Panel. **DO NOT TOUCH THE SCREEN.** The update process will take approximately 10 minutes. After the Panel reboots the home screen will appear and the LED will turn green.