

IQ PRO - 4.4.1n SOFTWARE UPDATE - RELEASE NOTES AND INSTRUCTIONS

TSB #: 260429

DATE: 04/29/26

RE: IQ PRO - 4.4.1n SOFTWARE UPDATE - RELEASE NOTES & INSTRUCTIONS

Release Notes:

New Features:

- Support for the HSM3204CX (Corbus Extender) has been added.
- New commercial sensor groups have been introduced, including:
 - Group 18: 24Hr Bell/Buzzer
 - Group 23: 24Hr Supervisory
 - Group 24: 24Hr Supervisory Buzzer
 - Group 27: 24Hr Fire Supervisory
 - Group 40: 24Hr Gas
 - Group 48: 24Hr Sprinkler
- Manual enrollment for MX devices is now supported.
- Remote diagnostics for Corbus modules are available.
- Remote enrollment for Prox tags has been implemented.
- PowerG+ sensor dealer lockdown capabilities have been added.
- Native support for the following PowerG+ devices is included:
 - PowerG+ IOG Module (PG ID 530 and 106)
 - PowerG+ Indoor PIR Camera (PG ID 145)
 - PowerG+ Smoke/Heat Detector (PG ID 205)
 - PowerG+ Water Tile (PG ID 242)
 - IQ Lock PG (PG ID 502)
 - IQ Light and IQ Dimmer (3-Way)
 - IQ IDP (UK W-Way)
- Remote over-the-air (OTA) support for Z-Wave devices has been added.
- Manual enrollment for MX devices is now supported.
- Remote diagnostics for Corbus modules are available.
- Remote enrollment for Prox tags has been implemented.
- Battery gauge reporting for PowerG+ devices is now available on the Alarm.com Partner Portal.
- A new jam state for water valves on specific Z-Wave shut-off valves has been introduced.
- Programming options now include the ability to disable the tamper feature on IQ Hardwire PowerG (PGxWLSHW8/PGxHRDW8) and PGP-IOx modules.

Fixes/Improvements:

- Fixed an issue where the IQ Installer App could intermittently fail to connect to the IQ Pro panel.
- Corrected an issue where Firmware updates for the HSM3105MX Module were not applying.
- Various system enhancements and fixes have been applied.
- Cybersecurity measures have been updated.

continued on Page 2...

IQ PRO - 4.4.1n SOFTWARE UPDATE - RELEASE NOTES AND INSTRUCTIONS

...continued from Page 1.

Update Instructions:

Compatibility Note: Your IQ Pro must be on software version 4.3.0n or higher and connected to Wi-Fi or Ethernet to install this update.

- 1- Connect to IQ Pro utilizing the IQ Installer Interface
- 2- Touch "Configuration"
- 3- Touch "Upgrade Software"
- 4- Touch "Patch Tag" and enter the patch **iqpro4.4.1n**
- 5- Touch "Yes, I want to upgrade" (panel must be connected to Wi-Fi or Ethernet). Update will download and install
- 6- The update process will take approximately 5 minutes. After the panel reboots reconnect the IQ Installer Interface